





MARK OIL LINES WITH A BRIGHT YELLOW
BAND 1/2" WIDE NEAR EACH END.
PART NO. TO BE PAINTED IN BLACK NEAR
EACH END.
USE CHAFING HOSE & FRIKTION TAPE WHERE
NECESSARY.
TAPE ALL HOSE UNDER CLAMPS.
USE PARKER "THERADOLUBE" GPE OR EQUIV.
ON ALL DUAL THERAZDS
ELECTRICAL BONDING SHALL BE IN ACCORDANCE
WITH DWS 28E1192.
ALL ALUM. ALLOY TUBE SPEC 44T-32 COND A (5230)
FINISH TUBES Z-P LATEL OUTSIDE.

- ① ALL PRESSURE LINES TO BE MARKED WITH LIGHT BLUE
LIGHT GREEN BANDS NEAR EACH END.
- ① P INDICATES PRESSURE
O OIL LINES



NOTE -
THIS INSTALLATION TO BE USED ON
FBY-3 SHIPS "0842 TO "0871 INCL. & "0901 TO "0907
INCL ONLY, ON FBY-4 ALL.
WHEN COMPLETE DE-ICING EQUIPMENT
IS INSTALLED.
SALES ORDER 925-31-1.

[illegible]

-8 PBY-5 18-0 302
-8 PBY-5 18-0 302
-3 PBY-4 28P3000
-2 PBY-4 28P3000
-3 PBY-3 28P3000
-2 PBY-3 28P3000

[illegible]